Infrastructure HSW Management Sub-System

Roof Inspection Check





Building Name: Oliphant Building No: NT 36 Date of Inspection 7/07/2023 Risk Keys Required: Roof Access Medium

Roof Access Details

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- Handrails are not a fall arrest system unless part of a submitted SWMS.

There is internal access to the main roof area from Level 5. Take stairs to locked roof doors.









Access Door

Plant

Roof walkways

Light on roof

<u>No access to areas without walkways</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Details		
Roof Material: Iron		No. of Roofs on Building: Main roof is divided into 4 sections plus a stairwell roof
Pitch: < 15° 15° to 30 > 30°	X near flat	Roof Height (m): Main – 6 storeys high
Gutter Details: Box Gutter External Gutter	□ X	Fragile Panels / areas: N/A
Access: Walkways Platforms Fixed Ladders	X Main roof □	Parapet Details (height, construction): Main roof protected by railing on all edges. Stairwell roof unprotected on all sides (no access).
Description of Roof Plan Air conditioners Spot/flood lights Ventilation ducts Experimental equipment Skylight	ıt:	Number: Numerous 6 Various Various 1
Other Details:		

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	July 2026	Page: 1 of 3	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01, Hazard Management\01 Roof Access\01 Ris	k Assessments\North	Terrace\2023\Oliph	ant\NT36 07-07-2	3 Oliphant -

Infrastructure HSW Management Sub-System

Roof Inspection Check



Risk Assessment

	Hazard	Risk Indicator once Controls in place	Control	
	Unprotected roof edges and height of roofs – Fall hazard	Rare x Severe Medium	Railing along the entire perimeter. No access to stair well roof.	
	Falling Objects	Rare x Severe Medium	Tool lanyards. Do not lean over edge will lose objects in pockets.	
Hazards	Walking on roof – Fall and slip hazard	Rare x Moderate Low	Take care when traversing. Walk and do not run. Wear protective footwear (refer below). Implement a safe system of work for prevention of falls prior to commencing works.	
	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard		Do not commence works in extreme weather conditions which will adversely affect workers.	
	Working alone	Slight x Major High	A system to ensure lone worker's welfare, needs to be in place.	
Other Information	 The method of access to rooftop shall depend on the specific job task being undertaken and risk assessme completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Method Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI); Access and work on roof top when weather is clear, dry and no high winds; Footwear must be toe steel capped and comply with AS/NZS 2210 for type 1 safety footwear; Sun protection policy and procedure is in place when working outdoors; Tools to be carried in tool belt; and Plant and equipment must be well maintained and serviced regularly. 			
nstructions	 Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub-System Roof Access Permit to be obtained prior to roof access; Ensure that tools are secured on their person or a safe work method for bringing tools to and from the task has been determined prior to commencement of job; and 			

<u>=</u>

- has been determined prior to commencement of job; and
 4. Do not carry out any tasks within/on an unguarded roof edge or fall hazard, unless a safe system of work is in place to ensure the risk of a fall has been minimised. CONSEQUENCES TABLE

	m process to encourse the new trees are
LIKELIHOOD	TABLE
Category	Description
Almost	There is an expectation that an event/incident will
certain	occur.
Likely	There is an expectation that an event/incident could
	occur but not certain to occur.
Slight	This expectation lies somewhere in the midpoint
	between "could" and "improbable"
Unlikely	There is an expectation that an event/incident is
	doubtful or improbable to occur
Rare	there is no expectation that the event/incident will
	occur

CONSEQUENCES TABLE				
Category	Description			
Severe	Injury resulting in death, permanent incapacity			
Major	Injury requiring extensive medical treatment, hospitalisation, or activities could result in a Notifiable occurrence.			
Moderate	Injury requires formal medical treatment (hospital outpatient/doctors visit etc), activities could result in an Improvement Notice.			
Minor	Injury requires first aid			
Negligible	Injury requires minor first aid (e.g. band aid), or result in short term discomfort (e.g. bruise, headache, muscular aches, etc)			

RISK RATING

Likelihood	Consequences					
	Negligible Minor Moderate Major Sev					
Almost Certain	Medium	High	Very High	Very High	Very High	
Likely	Medium	Medium	High	Very High	Very High	
Slight	Low	Medium	High	High	Very High	

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	July 2026	Page: 2 of 3	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Risk	k Assessments\North	Terrace\2023\Oliph	ant\NT36 07-07-2	3 Oliphant -

Infrastructure HSW Management Sub-System





Unlikely	Low	Low	Medium	Medium	High
Rare	Low	Low	Low	Medium	Medium

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	July 2026	Page: 3 of 3	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01, Hazard Management\01 Roof Access\01 Ris	k Assessments\North	Terrace\2023\Oliph	ant\NT36 07-07-2	23 Oliphant -