Infrastructure HSW Management Sub-System

Roof Inspection Check



Building Details

Building Name: Callaghan Building

Building No: RW020

Date of Inspection: 09/08/2023

Inherent Risk

Keys required:

Plant room & Roof access

Medium

Roof Access Details

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- A Lock Out/Tag Out procedure has been implemented for Fume Cupboards.
- Parapets are not a fall arrest system unless part of a submitted SWMS.

Enter Callaghan building, walk to far wall and turn left, open plant room door (G6), light is on the right side. An internal stairway leads to the roof door, a roof access key is required to open the door.











Ladder to door

Roof access door

Flume unit

Upper roof

Upper roof

<u>No access</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Details		
Roof Material: Spandel	(No. of Roofs on Building: 2 (upper (east and west) and lower)
Pitch: Near Flat (<5°)		Roof Height (m): Approximately 5 metres
Gutter Details: External Gutter Box Gutter	X X	Fragile Panels / areas: Nil
Access: Walkways Fixed Ladders	X X	Parapet Details (height, construction): 700mm in height lower roof
Description of Roof Pla Air conditioners 9 Fume vents 2 Extraction units 5 Spotlights 3 Tv Antenna 1	ant:	
Other Details:		al Manager de Constant de Cons

Potential for exposure to fumes - Liaise with Faculty Technical Manager to arrange appropriate timing for access.

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	August 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	August 2026	Page: 1 of 3	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	k Assessments\Rose	worthv\2023\Callagl	nan Building\RW0	20 09-08-23

Infrastructure HSW Management Sub-System

Roof Inspection Check



RISK ASSESSMENT

	Hazard	Risk Indicator once Controls in place	Control	
	Airbourne hazardous chemicals (Venting or Flumes)	Rare x Major Medium	Check with Building Owner and/or Laboratory Manager and undertake a risk assessment. Contact FM for details	
rds	Unprotected roof edges – Fall hazard	Rare x Severe Medium	No access to roof without a permit to work and a documented safe system of work.	
Hazards	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x Minor Low	Do not commence works in extreme weather conditions which will adversely affect workers.	
	Working alone	Slight x Major High	A system to ensure lone worker's welfare needs to be in place.	
	Slips and trips	Rare x Moderate Low	Wear safety boots and long trousers.	
Other Information	completed prior to commencement o Statement (SWMS) or Safe Work Proc 2. Access and work on roof top when wer 3. Footwear must be toe steel capped an 4. Sun protection policy and procedure is 5. Tools to be carried in tool belt; and	f work and include edure (SWP) and S ather is clear, dry a d comply with AS/N in place when work	nd no high winds; NZS 2210 for type 1 safety footwear; king outdoors;	
Instructions	 Plant and equipment must be well maintained and serviced regularly. Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub-System Roof Access Permit to be obtained prior to roof access; Venting or Fumes - airborne hazardous chemicals: check with Building Owner, Laboratory Manager and/or the Maintenance Service Centre and undertake a risk assessment; Ensure that tools are secured on their person or a safe work method for bringing tools to and from the task has been determined prior to commencement of job; and Do not carry out any tasks within on an unguarded roof edge or fall hazard, unless a safe system of work is in place to ensure the risk of a fall has been minimised. 			

LIKELIHOOD	TABLE
Category	Description
Almost	There is an expectation that an event/incident
certain	will occur.
Likely	There is an expectation that an event/incident
	could occur but not certain to occur.
Slight	This expectation lies somewhere in the
	midpoint between "could" and "improbable"
Unlikely	There is an expectation that an event/incident
	is doubtful or improbable to occur
Rare	there is no expectation that the event/incident
	will occur
DICK DATING	2

CONSEQUENCES TABLE				
Category	Description			
Severe	Injury resulting in death, permanent incapacity			
Major	Injury requiring extensive medical treatment,			
	hospitalisation, or activities could result in a			
	Notifiable occurrence.			
Moderate	Injury requires formal medical treatment			
	(hospital outpatient/doctors visit etc), activities			
	could result in an Improvement Notice.			
Minor	Injury requires first aid			
Negligible	Injury requires minor first aid (e.g. band aid), or			
	result in short term discomfort (e.g. bruise,			
	headache, muscular aches, etc)			
	•			

RISK RATING

Likelihood	Consequences							
	Negligible Minor Moderate Major Severe							
Almost Certain	Medium	High	Very High	Very High	Very High			

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	August 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	August 2026	Page: 2 of 3	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	k Assessments\Rose	worthy\2023\Callagh	nan Building\RW0	20 09-08-23

Infrastructure HSW Management Sub-System





Likely	Medium	Medium	High	Very High	Very High
Slight	Low	Medium	High	High	Very High
Unlikely	Low	Low	Medium	Medium	High
Rare	Low	Low	Low	Medium	Medium

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	August 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	August 2026	Page: 3 of 3	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	k Assessments\Rose	worthy\2023\Callagh	nan Building\RW0	20 09-08-23