Infrastructure Management Sub-System

Roof Inspection Check

of ADELAIDE

Building Details		
Building Name: Ingkarni Wardli Building No: NT 21	Date of Inspection: 26/07/2023	Inherent Risk
	Keys Required: Plant Room & Roof Access	Medium
Roof Access Details		

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- Handrails and parapets are not a fall arrest system unless part of a submitted SWMS.
- If using a harness all workers accessing the roof must have current Working at Heights training

Access is available by taking the lift to Level 7 and locating the fire exit stairwell opposite the lifts. Take the stairs up to the plant room door (Plant room key required), light is on left hand side when entering Plant Room. A roof access key is required to gain access to roof from the plant room(s).

A fixed ladder on the southern side of the building provides access to the plant room roof.







Roof 1 looking east



Roof 1 membrane area



Roof 1 rock area



Plant room roof ladder



dder Plant room roof

<u>No access to areas without walkways</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Details		
Roof Material: Iron / Membrane/ Rock		No. of Roofs on Building: Two - (Main consisting of iron, risen membrane platform and rock area plus iron plant room roof)
Pitch: < 15°	X	Roof Height (m): 7-8 storeys
Gutter Details: Box Gutter	X	Fragile Panels / areas:
Walkways	X Other:	Parapet Details (height, construction): Level 8: Railing, glass parapets
Fixed Ladders	X	Level 9: Railing and unprotected edges. Fixed ladder to plant room roof

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	July 2026	Page: 1 of 3	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	sk Assessments\Nort	h Terrace\2023\Ingk	arni Wardli\NT21	26-07-2023



Roof Inspection Check

Description of Roof Plant:
Infrastructure plant/ Solar panels
Air conditioners/Exhaust vents
Aerials/Bleed valves

Number: Various in plant room / 1 bank on north side Various Various Various

Other Details:

Plant room subdivided into multiple sections divided by locked doors. Plant room key accesses all sections

RISK ASSESSMENT

Nor	ASSESSIVIENT					
	Hazard	Risk Indicator once Controls in place	Control			
	Unprotected roof edges and height of roofs – Fall hazard	Rare x Severe Medium	No accessing unless a safe system of work for prevention of falls is implemented.			
ards	Walking on roof – Fall and slip hazard	Rare x Minor Low	Wear protective footwear (refer below). Implement a safe system of work for prevention of falls prior to commencing works.			
Hazards	Dropped objects.	Rare x Severe Medium	Tool lanyards. Do not lean over roof edges.			
	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x Minor Low	Do not commence works in extreme weather conditions which will adversely affect workers.			
	Working alone	Slight x Major High	A system to ensure lone worker's welfare needs, to be in place.			
Other Information	 The method of access to rooftop shall depend on the specific job task being undertaken and risk assessme completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Metho Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI); Access and work on roof top when weather is clear, dry and no high winds; Footwear must be toe steel capped and comply with AS/NZS 2210 for type 1 safety footwear; Sun protection policy and procedure is in place when working outdoors; Tools to be carried in tool belt; and Plant and equipment must be well maintained and serviced regularly. 					
Instructions	 Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub- System Roof Access Permit to be obtained prior to roof access; Ensure that tools are secured on their person or a safe work method for bringing tools to and from the has been determined prior to commencement of job; and Do not carry out any tasks within on an unguarded roof edge or fall hazard, unless a safe system of work 					

- 3. Ensure that tools are secured on their person or a safe work method for bringing tools to and from the task has been determined prior to commencement of job; and
 - 4. Do not carry out any tasks within on an unguarded roof edge or fall hazard, unless a safe system of work is in place to ensure the risk of a fall has been minimised.

LIKELIHOOD	LIKELIHOOD TABLE				
Category	Description				
Almost certain	There is an expectation that an event/incident will occur.				
Likely	There is an expectation that an event/incident could occur but not certain to occur.				
Slight	This expectation lies somewhere in the midpoint between "could" and "improbable"				
Unlikely	There is an expectation that an event/incident is doubtful or improbable to occur				
Rare	there is no expectation that the event/incident will occur				

CONSEQUENCES TABLE				
Category	Description			
Severe	Injury resulting in death, permanent incapacity			
Major	Injury requiring extensive medical treatment,			
	hospitalisation, or activities could result in a Notifiable occurrence.			
Moderate	Injury requires formal medical treatment (hospital			
	outpatient/doctors visit etc), activities could result in			
	an Improvement Notice.			
Minor	Injury requires first aid			
Negligible	Injury requires minor first aid (e.g. band aid), or result in short term discomfort (e.g. bruise, headache, muscular aches, etc)			

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	July 2026	Page: 2 of 3	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	sk Assessments\Nort	h Terrace\2023\Ingk	arni Wardli\NT21	26-07-2023


Infrastructure Management Sub-System



Roof Inspection Check

RISK RATING	RISK RATING								
Likelihood		Consequences							
	Negligible	Negligible Minor Moderate Major Severe							
Almost Certain	Medium	High	Very High	Very High	Very High				
Likely	Medium	Medium	High	Very High	Very High				
Slight	Low	Medium	High	High	Very High				
Unlikely	Low	Low	Medium	Medium	High				
Rare	Low	Low	Low	Medium	Medium				

Building Schematic – NT21 Ingkarni Wardli



💿 Unknown Anchor

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	July 2026	Page: 3 of 3	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	sk Assessments\Nort	h Terrace\2023\Ingk	arni Wardli\NT21	26-07-2023