### Infrastructure Management Sub-System

### **Roof Inspection Check**



Dulluling Details		
Building Name: Ligertwood	Date of Inspection: 21/07/2023	Risk
Building Name: Ligertwood Building No: NT 26	Keys required: Roof and Plant room access	Medium
uilding Name: Ligertwood		

#### Roof Access Details

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- If using a harness attached to an anchor point/static line all workers must have current Working at Heights training and anchor points/static lines must have been certified in the last 12 months.
- Parapets are not a fall arrest system unless part of a submitted SWMS.

#### Level 5 Roof

To access level 5 roof, enter stairwell open cleaners' door (502a) and climb metal steps. Exit through door.





Door 502a

#### Main Roof

To access main roof, enter stairwell (level 5), go through entrance door to male toilets, on the right hand side will be door number 601. Open door, climb stairs, turn right at end of stairs and follow the wall until you reach the metal louvre door.





Door 601

Staircase



Metal louvre door

<u>No access to areas without walkways/platforms</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Details	
Roof Material:	No. of Roofs on Building:
Iron	Two (2) –
	One main roof and one side roof

 Warning
 This process is uncontrolled when printed. The current version is available on the I&TS Website.
 Effective
 July 2023
 Version:
 3.0

 Authorised
 Director, Capital Projects & Facilities Management | Infrastructure Branch | Division of University
 Review
 July 2026
 Page: 1 of 3

 Filepath
 S:\Services\_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01
 Risk Assessments\North Terrace\2023\Ligertwood\NT26
 21-07-23

# Infrastructure Management Sub-System

## **Roof Inspection Check**



<b>Pitch:</b> Near flat <15°		Roof Height (m): Five storeys high
Gutter Details: Box Gutter External Gutter	X X	<b>Fragile Panels / areas:</b> 2 Skylights
Walkways	X - Level 5	Parapet Details (height, construction):
Anchor Points Other:	X – Level 5 & Main Roof	Parapet of various heights – Level 5
Description of Roof Plan Air conditioners Skylights Venting pipes	nt:	<b>Number:</b> Various Various
Other Details:		

### **Risk Assessment**

	Hazard	Risk Indicator once Controls in place	Control		
	Unprotected roof edges and height of roofs – Fall hazard	Rare x Severe Medium	No access to roof unless under a work permit and a safe system of work for prevention of falls is implemented		
sp	Access/Egress via window – muscle strain.	Rare x moderate Low	Do not rush and take time to access and egress via window.		
Hazards	Walking on level 5 roof –Slips, trips and collision with plant	Rare x Minor Low	Take care when traversing. Walk and do not run. Wear protective footwear (refer below). Implement a safe system of work for prevention of falls prior to commencing works.		
	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x moderate Low	Do not commence works in extreme weather conditions which will adversely affect workers.		
	Working alone	Slight x Major High	A system to ensure lone worker's welfare, needs to be in place.		
<ol> <li>The method of access to rooftop shall depend on the specific job task being undertaken and risk assessment completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Method Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI);</li> <li>Access and work on roof top when weather is clear, dry and no high winds;</li> <li>Footwear must be toe steel capped and comply with AS/NZS 2210 for type 1 safety footwear;</li> <li>Sun protection policy and procedure is in place when working outdoors;</li> <li>Tools to be carried in tool belt; and</li> <li>Plant and equipment must be well maintained and serviced regularly.</li> </ol>					
Instructions	1. Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub-				
	OOD TABLE		EQUENCES TABLE		
Category	y Description	Catego	bry Description		

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University	Review	July 2026	Page: 2 of 3	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01	Risk Assessments	North Terrace 202	3\Ligertwood\NT2	6 21-07-23

## Infrastructure Management Sub-System



## **Roof Inspection Check**

Almost certain		ere is an expectation that a	an event/incident will	Severe	Injury resulting in death, permanent incapacity			
Likely	Th	ere is an expectation that a cur but not certain to occu		Major	Injury requiring extensive medical treatment, hospitalisation, or activities could result in a Notifiable			
Slight	Deckin but not certain to occur.         Inspiralisation, of activities could result if a resu					treatment (hospital		
Unlikely	Th	ere is an expectation that a ubtful or <b>improbable</b> to oc	an event/incident is					
Rare	the	ere is no expectation that the transformer of the t	ne event/incident will	Negligible	ble Injury requires minor first aid (e.g. band aid), or result in short term discomfort (e.g. bruise, headache,			
<b>RISK RATIN</b>								
Likelihood				Consequence	S			
		Negligible	Minor	Moderate	Major	Severe		
Almost Cert	ain	Medium	High	Very High	Very High	Very High		
Likely		Medium	Medium	High	Very High	Very High		
Slight		Low	Medium	High	High	Very High		
Unlikely		Low	Low	Medium	Medium	High		
Rare		Low	Low	Low	Medium	Medium		

Location of anchors.

Green - Purlin Mount Fall arrest anchor. x 8 Blue - Purlin Mount Abseil anchor. x 26 Yellow -Surface Mount Fall Arrest anchor. x 6



Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authoris	Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University	Review	July 2026	Page: 3 of 3	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access	01 Risk Assessment	s\North Terrace\202	3\Ligertwood\NT26	21-07-23