Infrastructure HSW Management Sub-System

Roof Inspection Check



Building Details		
Building Name: Madley Building Building No: NT32	Date of Inspection: 03/08/2023	Risk
	Keys Required: Security can only open door	Medium

Roof Access Details

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- If using a harness attached to an anchor point/static line, all workers must have current Working at Heights training and anchor points/static lines must have been certified in the last 12 months.

To access main roof area, enter Scott Theatre on the ground level, go to back of stage area, lights can be turned on via light control panel which is on the right side as you enter backstage area (see photo). Climb stairs on western side (left hand side as you enter backstage area) that leads to a locked door (security are required to open this door) and climb down the outside stairs onto the roof.

Access to the veranda roof is via a ladder from the Pfitzner courtyard.











Light Control Panel Ladder to external access External steps onto Madley

Veranda - Madley

No access to areas without walkways unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Details	
Roof Material:	No. of Roofs on Building: Two
Pitch: Main Roof: Near flat <5 ° Veranda: Counter level pitch	Roof Height (m): Main Roof: 18m Veranda: 8m approx
Gutter Details: Box Gutter ☑	Fragile Panels / areas:
Walkways ☑ Platforms ☑	Parapet Details (height, construction):
Description of Roof Plant: Main Roof: Air Conditioners, exhaust units, venting pipes	Number: Several
Other Details:	

nor point present western side off plant platform (installed 20/3/07).

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	August 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	August 2026	Page: 1 of 2	
Filepath S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Risk Assessments\North Terrace\2023\Madley\NT32 03-08-23 Madley-					

Infrastructure HSW Management Sub-System

Roof Inspection Check



RISK ASSESSMENT

Hazards	Hazard	Risk Indicator once controls in place	Control	
	Unprotected roof edges and height of roofs – Fall hazard	Rare x Severe Medium	No access to roof unless under a work permit and a safe system of work for prevention of falls is implemented	
	Walking on roof – Fall and slip hazard	Rare x Minor Low	Take care when traversing. Walk and do not run. Wear protective footwear (refer below). Implement a safe system of work for prevention of falls prior to commencing works.	
	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x Moderate Low	Do not commence works in extreme weather conditions which will adversely affect workers. Wear a hat in open sun.	
	Working alone	Slight x Major High	A system to ensure lone worker's welfare, needs to be in place.	
Other Information	 The method of access to rooftop shall depend on the specific job task being undertaken and risk assessment completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Method Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI); Access and work on roof top when weather is clear, dry and no high winds; Footwear must be toe steel capped and comply with AS/NZS 2210 for type 1 safety footwear; Sun protection policy and procedure is in place when working outdoors; Tools to be carried in tool belt; and Plant and equipment must be well maintained and serviced regularly. 			
Instructions	 Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub-System Roof Access Permit to be obtained prior to roof access; Ensure that tools are secured on their person or a safe work method for bringing tools to and from the task has been determined prior to commencement of job; and Do not carry out any tasks within/on an unguarded roof edge or fall hazard, unless a safe system of work is in place to ensure the risk of a fall has been minimised. 			

	in place to choose the not of a fail has been				
LIKELIHOOD .	LIKELIHOOD TABLE				
Category	Description				
Almost	There is an expectation that an event/incident will				
certain	occur.				
Likely	There is an expectation that an event/incident could				
	occur but not certain to occur.				
Slight	This expectation lies somewhere in the midpoint				
	between "could" and "improbable"				
	·				
Unlikely	There is an expectation that an event/incident is				
	doubtful or improbable to occur				
Rare	there is no expectation that the event/incident will				
	occur				

CONSEQUEN	CONSEQUENCES TABLE				
Category	Description				
Severe	Injury resulting in death, permanent incapacity				
Major	Injury requiring extensive medical treatment,				
	hospitalisation, or activities could result in a Notifiable				
	occurrence.				
Moderate	Injury requires formal medical treatment (hospital				
	outpatient/doctors visit etc), activities could result in				
	an Improvement Notice.				
Minor	Injury requires first aid				
Negligible	Injury requires minor first aid (e.g. band aid), or result				
	in short term discomfort (e.g. bruise, headache,				
	muscular aches, etc)				

RISK RATING

Likelihood	Consequences				
	Negligible	Minor	Moderate	Major	Severe
Almost Certain	Medium	High	Very High	Very High	Very High
Likely	Medium	Medium	High	Very High	Very High
Slight	Low	Medium	High	High	Very High
Unlikely	Low	Low	Medium	Medium	High
Rare	Low	Low	Low	Medium	Medium

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	August 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management Infrastructure Branch Division of University	Review	August 2026	Page: 2 of 2	
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 R	isk Assessments\North	Terrace\2023\Ma	adlev\NT32 03-08	-23 Madlev-