### Infrastructure Management Sub-System

### **Roof Inspection Check**

#### **Building Details**

Building Name: Barr Smith Library North Building No: NT07

19/07/2023 Keys required: Plant Room & Roof Access

Date of Inspection:

Risk

Medium

#### **Roof Access Details**

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- · Parapets are not a fall arrest system unless part of a submitted SWMS.
- If using a harness attached to an anchor point/static line all workers must have current Working at Heights training and anchor points/static lines must have been certified in the last 12 months.

There is internal access to **main roof Level 6**. Enter Barr Smith Library (main entrance - level 3) turn left and follow white vinal floor tiles to Northern stairwell. Go to level 5 and access plant room (no 507) with plant room key. Go upstairs and access roof through an unlocked door. Unlocked door requires a plant room key to open it from the outside.







Main roof

To access **Eastern Plant deck** go through wall hatch on level 5 (Refer photograph). A plant access key is required. Use the custom ladder to access the ceiling space and proceed to the roof hatch/skylight via walkway. A roof access key is required to unlock the hatch.



Level 5 entry hatch



Level 5 hatch/skylight



Various Anchor Points

<u>No access to areas without walkways</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University	Review	July 2026	Page: 1 of 3	
Filepath	S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Ris	k Assessments\North	Terrace\2023\Barr S	Smith North\NT07	19-07-2023



# Infrastructure Management Sub-System

# **Roof Inspection Check**



Roof Details	
<b>Roof Material:</b> Membrane on L6 and plant roofs. Colorbond steel and Terracotta tiles.	<b>No. of Roofs on Building:</b> Five Main roof, Plant roof, plant deck, steel & terracotta roofs.
<b>Pitch:</b> Main roof, Plant roof and plant deck level. Steel and terracotta roofs vary.	Roof Height (m): 4 stories
Gutter Details: External Gutter X Stairwell Roof	Fragile Panels / areas:
Walkways  Platforms	Parapet Details (height, construction): Main roof – brick parapet 1200mm
Fixed Ladders  Other: Stairwell lift roof is unprotected	Plant room roof has 600mm parapet
<b>Description of Roof Plant:</b> Main Roof – range of plant including Air Conditioners & Cooling towers etc Plant Room roof – exhaust fans	<b>Number:</b> Various Various
Other Details: No plant on lift motor room roof and stairwell r	oof

### **RISK ASSESSMENT**

Hazards	Hazard	Risk Indicator once Controls in place	Control			
	Unprotected roof edges and height of roofs – Fall hazard	Rare x Severe Medium	No access to roof unless under a work permit and a safe system of work for prevention of falls is implemented.			
	Walking on roof – Slip and fall hazard	Rare x Minor Low	Plant area surrounded by parapet. Take care when traversing. Walk and do not run. Wear protective footwear (refer below).			
Ĩ	Colliding with fixed plant	Rare x Minor Low	Conduct visual inspection prior to commencing works. Identify potential sources of collision.			
	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x Minor Low	Do not commence works in extreme weather conditions which will adversely affect workers. Enact communication protocol if working alone.			
	Working alone	Slight x Major High	A system to ensure lone worker's welfare, needs to be in place.			
Other Information	<ol> <li>The method of access to rooftop shall depend on the specific job task being undertaken and risk assessment completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Method Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI);</li> <li>Access and work on roof top when weather is clear, dry and no high winds;</li> <li>Footwear must be toe steel capped and comply with AS/NZS 2210 for type 1 safety footwear;</li> <li>Sun protection policy and procedure is in place when working outdoors;</li> <li>Tools to be carried in tool belt; and</li> <li>Plant and equipment must be well maintained and serviced regularly.</li> </ol>					
Instructions	<ol> <li>Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub-System</li> <li>Roof Access Permit to be obtained prior to roof access;</li> <li>Ensure that tools are secured on their person or a safe work method for bringing tools to and from the task has been determined prior to commencement of job; and</li> <li>Do not carry out any tasks within/on an unguarded roof edge or fall hazard, unless a safe system of work is in place to ensure the risk of a fall has been minimised.</li> </ol>					

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0	
Authorised	Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University	Review	July 2026	Page: 2 of 3		
Filepath S:\Services_Resources\Infrastructure\SharedIHSW\01. Hazard Management\01 Roof Access\01 Risk Assessments\North Terrace\2023\Barr Smith North\NT07 19-07-2023						

## Infrastructure Management Sub-System





LIKELIHOOD TABLE							
Category	ory Description						
Almost	Th	ere is an expectation that	an event/incident will				
certain	ос	cur.					
Likely	Th	ere is an expectation that	an event/incident <b>could</b>				
	oc	cur but not certain to occu	ır.				
Slight	Th	This expectation lies somewhere in the midpoint					
	be	tween "could" and "improb	able"				
Unlikely	Th	There is an expectation that an event/incident is					
	doubtful or improbable to occur						
Rare	there is no expectation that the event/incident will						
	OC	occur					
RISK RATING	<u> </u>						
	,						
Likelihood							
		Negligible	Minor				
Almost Certain		Medium	High				

CONSEQUENCES TABLE						
Category	Description					
Severe	Injury resulting in death, permanent incapacity					
Major	Injury requiring extensive medical treatment,					
	hospitalisation, or activities could result in a Notifiable					
	occurrence.					
Moderate	Injury requires formal medical treatment (hospital					
	outpatient/doctors visit etc), activities could result in					
	an Improvement Notice.					
Minor	Injury requires first aid					
Negligible	Injury requires minor first aid (e.g. band aid), or result					
	in short term discomfort (e.g. bruise, headache,					
	muscular aches, etc)					

Likelihood Consequences						
Likelinood	Negligible Minor Moderate Major					
Almost Certain	Medium	High	Very High	Very High	Very High	
Likely	Medium	Medium	High	Very High	Very High	
Slight	Low	Medium	High	High	Very High	
Unlikely	Low	Low	Medium	Medium	High	
Rare	Low	Low	Low	Medium	Medium	

Warning	This process is uncontrolled when printed. The current version is available on the I&TS Website.	Effective	July 2023	Version:	3.0	
Authorised	Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University	Review	July 2026	Page: 3 of 3		
Filepath S:\Services_Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Risk Assessments\North Terrace\2023\Barr Smith North\NT07 19-07-2023						