## Infrastructure HSW Management Sub-System

## **Roof Inspection Check**



Building Details		
Building No: NT 33	Date of Inspection: 21/09/2023	Risk
	Keys Required: Roof Access	Medium

### **Roof Access Details**

- Right of Access Permit is only for visual inspection and a different permit is required before commencing any work on the roof.
- If using a harness attached to an anchor point/static line all workers must have current Working at Heights training and anchor points/static lines must have been certified in the last 12 months.

There is internal access from Level 2 of the Napier Building. Entry is from corridor at the western end. Access to the roof is through the locked glass doors adjacent to fire safety door on level 2.









Access door

Courtyard

Eastern plant

Western plant

<u>No access to roof</u> unless a safe system of work is in place to ensure the risk of a fall has been minimised (2012 SA WHS Regulations Part 4), this could include using industrial fall arrest harness attached to the static lines or anchor points if available.

Roof Details		
Roof Material: Membrane		No. of Roofs on Building: One (1)
Pitch: Near flat <15°		Roof Height (m): Two storeys high
Gutter Details: Box Gutter Other:		Fragile Panels / areas: Unstable floor within open plant area.
Walkways Platforms Fixed Ladders Other: Nil	N/A N/A N/A	Parapet Details (height, construction): N/A
<b>Description of Roof Pla</b> Air conditioners Locked plant area	nt:	Number: Various Various
Other Details: Anchor points installed.		

#### **RISK ASSESSMENT**

Hazards	Hazard	Risk Indicator once Controls in place	Control	
	Unprotected roof edges and height of roofs – Fall hazard.	Rare x Severe Medium	Do not carry out any tasks at an unguarded roof edge, unless a safe system of work for prevention of falls is implemented.	
	Unstable floor area in open plant area – Tripping hazard	Rare x Minor Low	Do not walk on unstable area Plan path of travel prior to commencing work	

Warning	Warning This process is uncontrolled when printed. The current version is available on the I&TS Website.		September 2023	Version:	3.0
Authorised	d Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University		September 2026	Page: 1 of 2	
Filepath	Filepath S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Risk Assessments\North Terrace\2023\Lower Napier\NT33 Lower Napier				

# Infrastructure HSW Management Sub-System

# **Roof Inspection Check**



	Walking on roof – Fall and slip hazard	Rare x Minor Low	Take care when traversing.  Walk and do not run.  Wear protective footwear (refer below).  Implement a safe system of work for prevention of falls prior to commencing works.	
	Weather – Heat, rain, strong winds – Heat exhaustion, dehydration, sunburn, colds, fall hazard	Rare x Moderate Low	Do not commence works in extreme weather conditions which will adversely affect workers. Avoid working alone. Communication protocol.	
	Working alone	Slight x Major High	A system to ensure lone worker's welfare, needs to be in place.	
Other Information	<ol> <li>The method of access to rooftop shall depend on the specific job task being undertaken and risk assessment completed prior to commencement of work and included in Job Safety Analysis (JSA) or Safe Work Method Statement (SWMS) or Safe Work Procedure (SWP) and Safe Work Instruction (SWI);</li> <li>Access and work on roof top when weather is clear, dry and no high winds;</li> <li>Footwear must be toe steel capped and comply with AS/NZS 2210 for type 1 safety footwear;</li> <li>Sun protection policy and procedure is in place when working outdoors;</li> <li>Tools to be carried in tool belt; and</li> <li>Plant and equipment must be well maintained and serviced regularly.</li> </ol>			
Instructions	<ol> <li>Undertake roof access in accordance with the University of Adelaide Infrastructure Management Sub-System</li> <li>Roof Access Permit to be obtained prior to roof access;</li> <li>Ensure that tools are secured on their person or a safe work method for bringing tools to and from the task has been determined prior to commencement of job; and</li> <li>Do not carry out any tasks within/on an unguarded roof edge or fall hazard, unless a safe system of work is in place to ensure the risk of a fall has been minimised.</li> </ol>			

LIKELIHOOD	LIKELIHOOD TABLE		
Category	Description		
Almost	There is an expectation that an event/incident will		
certain	occur.		
Likely	There is an expectation that an event/incident <b>could</b>		
	occur but not certain to occur.		
Slight	This expectation lies somewhere in the midpoint		
	between "could" and "improbable"		
	·		
Unlikely	There is an expectation that an event/incident is		
	doubtful or improbable to occur		
Rare	there is no expectation that the event/incident will		
	occur		

CONSEQUENCES TABLE				
Category	Description			
Severe	Injury resulting in death, permanent incapacity			
Major Injury requiring extensive medical treatment, hospitalisation, or activities could result in a Notifial occurrence.				
Moderate	Injury requires formal medical treatment (hospital outpatient/doctors visit etc), activities could result in an Improvement Notice.			
Minor	Injury requires first aid			
Negligible	Injury requires minor first aid (e.g. band aid), or result in short term discomfort (e.g. bruise, headache, muscular aches, etc)			

## **RISK RATING**

Likelihood	Consequences				
	Negligible	Minor	Moderate	Major	Severe
Almost Certain	Medium	High	Very High	Very High	Very High
Likely	Medium	Medium	High Very High		Very High
Slight	Low	Medium	High	High	Very High
Unlikely	Low	Low	Medium	Medium	High
Rare	Low	Low	Low	Medium	Medium

Warning	/arning This process is uncontrolled when printed. The current version is available on the I&TS Website.		September 2023	Version:	3.0
Authorised	Director, Capital Projects & Facilities Management   Infrastructure Branch   Division of University	Review Date:	September 2026	Page: 2 of	2
Filepath	S:\Services Resources\Infrastructure\Shared\HSW\01. Hazard Management\01 Roof Access\01 Risk Assessments\North Terrace\2023\Lower Napier\NT33 Lower Napier				