



9th January 2019

Certificate of Compliance

University of Adelaide North Terrace Campus Building NT20 – The Braggs (external)

Inspected to comply with AS1891.4-2009 Industrial fall arrest systems and devices- Part 4: Selection, use and maintenance.

SYSTEMS IN PLACE:

LOCATION: NT20 The Braggs Roof

3x STATIC SAFETY LINE:

System ID: NT20-SL-01
NT20-SL-02 (Tagged, out of service, System No longer Required)
NT20-SL-03

LOCATION: NT20 The Braggs Roof

5x SURFACE MOUNTED ANCHOR:

System ID: NT20-SMAP-01
NT20-SMAP-02
NT20-SMAP-03
NT20-SMAP-04
NT20-SMAP-05

LOCATION: NT20 The Braggs Roof South

15x PURLIN MOUNTED ANCHOR:

System ID: NT20-PA-01
NT20-PA-02
NT20-PA-03
NT20-PA-04
NT20-PA-05
NT20-PA-06
NT20-PA-07
NT20-PA-08
NT20-PA-09
NT20-PA-10
NT20-PA-11
NT20-PA-12
NT20-PA-13
NT20-PA-14
NT20-PA-15

LOCATION: NT20 The Braggs Roof North West Corner
2x MECHANICAL ANCHOR:

System ID: NT20-MA-21
NT20-MA-22

LOCATION: NT20 The Braggs Roof Rock Scree South East

3 x Anchor NT20-MA-15
NT20-MA-16
NT20-MA-17

LOCATION: NT20 The Braggs Roof Rock Scree South West

3 x Anchor NT20-MA-18
NT20-MA-19
NT20-MA-20

LOCATION: NT20 The Braggs Level 5 East

2x Davit Arm NT20-DA-01 (Locking pins Replaced 11/1/2018)
NT20-DA-02 (Locking pins Replaced 11/1/2018)

14X Davit Socket NT20-DC-01
NT20-DC-02
NT20-DC-03
NT20-DC-04
NT20-DC-05
NT20-DC-06
NT20-DC-07
NT20-DC-08
NT20-DC-09
NT20-DC-10
NT20-DC-11
NT20-DC-12
NT20-DC-13
NT20-DC-14

14X Anchor NT20-MA-1
NT20-MA-2
NT20-MA-3
NT20-MA-4
NT20-MA-5
NT20-MA-6
NT20-MA-7
NT20-MA-8
NT20-MA-9
NT20-MA-10
NT20-MA-11
NT20-MA-12
NT20-MA-13
NT20-MA-14

Inspection date Pass: 19/12/2019

Next Inspection due: 19/12/2020

Harrison Webb
Vertigo High Access Services